


Memory Card



damaged card
and
exposed copper




damaged card



seriously cracked cards

Memory Module



broken PCB



gold finger seriously damaged



burned gold fingers




Team Group Inc

Unusual Damage Inspection Standard

Version : 4



inconsistent information with the memory module




damaged IC


Solid State Drive



burned connecting fingers



pulled apart SSD and
anti-tearing label missing /
interior inconsistent PCBA after
manufacturing



cracked circuit board



pulled apart IC



Team Group Inc

Unusual Damage Inspection Standard

Version : 4



damaged IC




melted connecting fingers




USB Drives



bent USB connector



bent USB



USB drive without case

Mobile Accessory

cracked plastic headpiece



cracked lightning

Remark: There are many cases about unusual damage caused on the product. We take some examples and update irregularly for your reference. Please refer to our relevant warranty statements on our website [here](#) for more information. Please note that TEAM GROUP reserves the right for final inspection.